

# CONSTRUCTION EQUIPMENT VOLVO A40G 342659 - DROP BOX



Sample No: VCP0007813

**Oil Type:** GEAR OIL SAE 80W140

Job No:

VOLVO SAMPLE	INFORMATIO	N .		
Sample Number		VCP0007813	 	
Sample Date		29 Mar 2024	 	
Machine Hours		0	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		ABNORMAL	 	
		ADITORIVIAL		
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	<b>□</b> 297	 	
COLVO	IINATION			
_				
Water	%	NEG	 	
Silicon	ppm	<b>2</b> 4	 	
Sodium	ppm	<b>1</b> 4	 	
Potassium	ppm	<b>■</b> 3	 	
VOLVO				
WEAR M	ETALS			
Iron	ppm	<u> </u>	 	
Copper	ppm	<u></u> 40	 	
Lead	ppm	■0	 	
Tin	ppm	<b>■</b> <1	 	
Aluminum	ppm	<b>1</b>	 	
Chromium	ppm	<b>8</b>	 	
Molybdenum	ppm	<b>7</b>	 	
Nickel		2	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<b>□</b> 12	 	
Vanadium		0	 	
variaulum	ppm	U		
VOLVO			 	
<b>ADDITIV</b>	EZ			
Calcium	ppm	<b>■</b> 93	 	
Magnesium	ppm	<b>11</b>	 	
Zinc	ppm	<b>196</b>	 	
Phosphorus	ppm	<b>1022</b>	 	
Barium	ppm	<b>0</b>	 	
Boron	ppm	<b>66</b>	 	
		_		



#### **ALTA EQUIPMENT COMPANY**

8750 PHILIPS HWY JACKSONVILLE, FL US 32256

Contact: TECHNICIAN ACCOUNT catherine.anastasio@wearcheck.com

1:

F: (904)737-1260

### Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.Bearing and/or gear wear is indicated. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0092Unique No:10962585Signed:Sean FeltonReport Date:05 Apr 2024

Submitted By: TECHNICIAN ACCOUNT



## **CONSTRUCTION EQUIPMENT**





