



CONSTRUCTION EQUIPMENT

VOLVO A40G 342660 - COOLANT



Sample No: VCP0007796

Oil Type: {unknown}

Job No:



SAMPLE INFORMATION

Sample Number	VCP0007796	---	---	---
Sample Date	29 Mar 2024	---	---	---
Machine Hours	5381	---	---	---
Sample Status	NORMAL	---	---	---



COOLANT CONDITION

pH	Scale 0-14	■ 7.94	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 56.5	---	---	---
Freezing Point	°C	■ -50	---	---	---



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

ALTA EQUIPMENT COMPANY
 8750 PHILIPS HWY
 JACKSONVILLE, FL
 US 32256
 Contact: TECHNICIAN ACCOUNT
 catherine.anastasio@wearcheck.com
 T:
 F: (904)737-1260

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot: VOLVO0092
Unique No: 10962669
Signed: Jonathan Hester
Report Date: 08 Apr 2024

Submitted By: TECHNICIAN ACCOUNT



CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver



Reserve Alkalinity



Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

