



CONSTRUCTION EQUIPMENT

VOLVO A40G 342 I 12 - COOLANT



Sample No: VCP0007906
Oil Type: HYBRID (HOAT) COOLANT
Job No:



SAMPLE INFORMATION

Sample Number	VCP0007906	VCP0006350	---	---
Sample Date	29 Mar 2024	07 Feb 2023	---	---
Machine Hours	7550	7550	---	---
Sample Status	NORMAL	NORMAL	---	---

ALTA EQUIPMENT COMPANY
 8750 PHILIPS HWY
 JACKSONVILLE, FL
 US 32256
 Contact: SHAWN NORTHCRAFT
 shawn.northcraft@altg.com
 T: (904)737-6000
 F: (904)737-1260



COOLANT CONDITION

pH	Scale 0-14	7.67	7.48	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	NT	NT	---	---
Percentage Glycol	%	47.5	47.3	---	---
Freezing Point	°C	-28	-28	---	---

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

Coolant Appearance	normal	normal	---	---
Coolant Color	Yllow	Yllow	---	---

Depot: VOLVO0092
Unique No: 10962671
Signed: Jonathan Hester
Report Date: 08 Apr 2024



CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity



Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

