CONSTRUCTION EQUIPMENT 3022 VOLVO EC380EL 311273 - FRONT RIGHT FINAL DRIVE

Sample No: VCP432786

VOLVO

| Oil Type: | VOLVO PREMIUM GEAR OIL 80W-90 GL-5 |
|-----------|------------------------------------|
| Job No: | 3022 |

SAMPLE INFORMATION VCP432786 Sample Number Sample Date 25 Mar 2024 Machine Hours 6130 Oil Hours 0 Oil Changed Not Changd NORMAL Sample Status **OIL CONDITION** Visc @ 40°C cSt 147 CONTAMINATION Water % NEG Silicon ppm 12 Sodium 1 🔲 ppm Potassium ppm 2 WEAR METALS 222 Iron ppm Copper ppm 6 Lead ppm 0 🔲 Tin ppm **||** <1 Aluminum ppm 2 Chromium 3 ppm Molybdenum ppm **<**1 Nickel ■ <1 ppm Titanium <1 ppm Silver 0 ppm Manganese ppm 3 Vanadium ppm 0

| | /£3 | | | |
|------------|-----|------------|------|--|
| Calcium | ppm | 100 | | |
| Magnesium | ppm | 2 | | |
| Zinc | ppm | 56 | | |
| Phosphorus | ppm | 1735 | | |
| Barium | ppm | 0 | | |
| Boron | ppm | 113 | | |



LEONARDS CONTRACTING

30850 STEPHENSON HWY MADISON HEIGHTS, MI US 48071 Contact: LARRY SCHRADE larry.schrade@sdevelop.com T: (810)499-1953 F: x:

Diagnosis


Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:LEOMADUnique No:10963652Signed:Wes DavisReport Date:05 Apr 2024Contact/Location:LARRY SCHRADE - LEOMAD

CONSTRUCTION EQUIPMENT



VOLVO



Report Id: LEOMAD [WUSCAR] 06138844 (Generated: 04/09/2024 15:07:52) Rev: 1