

CONSTRUCTION EQUIPMENT SW0-070729 EPIROC D60-10 TMG23SED0506 - COMPRESSOR

Sample No: VCP436283 Oil Type: {unknown} Job No: SWO-070729

VOLVO SAMPLE	INFORMATION	N		
	INI OMPATIO		V(CD 4 400 4 4	 <u>.</u>
Sample Number		VCP436283	VCP449244	
Sample Date		01 Apr 2024	27 Dec 2023	
Machine Hours		558	263	
Oil Hours		0	0	
Oil Changed		Not Changd	Not Changd	
Sample Status		NORMAL	ABNORMAL	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	199	67.5	
VOLVO	UNIA TION			
LUNTAM	IINATION			
Water	%	NEG	NEG	
Silicon	ppm	4	0	
Sodium	ppm	5	0	
Potassium	ppm	2	0	
WEAR M	ETAL C			
_	ETAL2			
Iron	ppm	2	□0	
Copper	ppm	■<1	0	
Lead	ppm	■<1	0	
Tin	ppm	■<1	0	
Aluminum	ppm	2	<u> </u>	
Chromium	ppm	■<1	1	
Molybdenum	ppm	<1	0	
Nickel	ppm	<1	0	
Titanium	ppm	<1	0	
Silver	ppm	0	0	
Manganese	ppm	<1	0	
Vanadium	ppm	<1	0	
ADDITIV	FS			
Calcium	-	24	8	
	ppm			
Magnesium	ppm	3	0	
Zinc	ppm	367	16	
Phosphorus	ppm	288	55	
Barium	ppm	0	4	
Boron	ppm	0	0	



WHITAKER CONTRACTING

692 CONVICT CAMP RD GUNTERSVILLE, AL US 35976 Contact: BROTHER WHITAKER Brother Whitaker@whitaker-contracting.comT: (256)298-3905

Diagnosis

F:

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: WHIGUN **Unique No:** 10963659 Signed: Don Baldridge Report Date: 06 Apr 2024



CONSTRUCTION EQUIPMENT





