

CONSTRUCTION EQUIPMENTSENNEBOGEN 825 825.0.3324 - FRONT LEFT FINAL DRIVE



Sample No: VCP440541

Oil Type: GEAR OIL SAE 80W90

Job No:

| VOLVO | INFORMATION | J | | | |
|----------------|-------------|---------------|--------------|---------------|--|
| | INFURMATIU | | | | |
| Sample Number | | VCP440541 | VCP370240 | VCP345145 | |
| Sample Date | | 28 Mar 2024 | 03 May 2023 | 06 Nov 2021 | |
| Machine Hours | | 11523 | 8745 | 5635 | |
| Oil Hours | | 0 | 0 | 0 | |
| Oil Changed | | Changed | Changed | Changed | |
| Sample Status | | NORMAL | NORMAL | NORMAL | |
| | | | | | |
| OIL CON | NITION | | | | |
| | | | | · | |
| Visc @ 40°C | cSt | 116 | □91.6 | □ 55.6 | |
| VOLVO | | | | | |
| CONTAN | IINATION | | | | |
| Water | % | NEG | NEG | NEG | |
| Silicon | | NEG | INEG | NEG ■8 | |
| Sodium | ppm | | | _ | |
| | ppm | 8 | □ 10 | □ 19 | |
| Potassium | ppm | 2 | 2 | ■0 | |
| VOLVO | | | | | |
| WEAR M | IETALS | | | | |
| Iron | ppm | 113 | 1 119 | □ 98 | |
| Copper | ppm | 13 | 1 7 | 1 44 | |
| Lead | ppm | - <1 | = <1 | 1 <1 | |
| Tin | ppm | ■<1 | - <1 | - <1 | |
| Aluminum | ppm | 1 | 1 0 | 1 <1 | |
| Chromium | ppm | - <1 | 1 | 1 | |
| Molybdenum | ppm | 1 | 2 | 2 | |
| Nickel | ppm | - <1 | _ <1 | 0 | |
| Titanium | ppm | <1 | 0 | <1 | |
| Silver | ppm | 0 | 0 | 0 | |
| Manganese | ppm | 2 | 2 | 2 | |
| Vanadium | ppm | 0 | 0 | 0 | |
| variation | ppiii | · · | U | U | |
| VOLVO | | | | | |
| ADDITIV | EZ | | | | |
| Calcium | ppm | 417 | 976 | 3220 | |
| Magnesium | ppm | 8 | 12 | 15 | |
| Zinc | ppm | 155 | 410 | 1329 | |
| Phosphorus | ppm | 930 | 590 | 1051 | |
| Barium | ppm | ■ 0 | 0 | 0 | |
| Boron | ppm | ■53 | 31 | 112 | |
| | - | | | | |



UNITED SCRAP
1545 S CICERO AVE
CICERO, IL
US 60804
Contact: RON LUCHTENBURG
rluchten@unitedscrap.com
T:
F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:UNICICILUnique No:10963683Signed:Don BaldridgeReport Date:06 Apr 2024



CONSTRUCTION EQUIPMENT





GRAPHS

