

# CONSTRUCTION EQUIPMENT SW-31591-2 RAMSEY VOLVO A60H 350374 - REAR AXLE

Sample No: VCP443092

Oil Type: VOLVO PREMIUM GEAR OIL 80W-90 GL-5

Job No: SW-31591-2 RAMSEY

VOLVO				
SAMPLE	<b>INFORMATION</b>			
Sample Number	_	VCP443092	 	
Sample Date		01 Apr 2024	 	
Machine Hours		522	 	
Oil Hours		522	 	
Oil Changed		Changed	 	
Sample Status		ATTENTION	 	
Sumple Status		711121111011		
VOLVO				
OIL COND	DITION			
Visc @ 40°C	cSt	<b>52.1</b>	 	
VOLVO				
CONTAM	INATION			
		NIFC		
Water	%	NEG	 	
Silicon	ppm	<b>2</b>	 	
Sodium	ppm	<b>1</b>	 	
Potassium	ppm	■0	 	
VOLVO				
WEAR M	FTALS			
Iron		<b>155</b>	 	
Copper	ppm	■ <1	 	
Lead	ppm	<b>0</b>	 	
Tin	ppm	<b>0</b>	 	
Aluminum	ppm	■0	 	
Chromium	ppm	<b>2</b>	 	
	ppm	2	 	
Molybdenum	ppm			
Nickel	ppm	0		
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<b>6</b>	 	
Vanadium	ppm	0	 	
VOLVO				
<b>ADDITIV</b>	ES			
Calcium	ppm	■314	 	
Magnesium	ppm	<b>1</b>	 	
Zinc	ppm	<b>146</b>	 	
Phosphorus	ppm	2319	 	
Barium	ppm	<b>0</b>	 	
Boron	ppm	276	 	
DOTOTI	ppiii			

#### ARNOLD MACHINERY COMPANY

2975 WEST 2100 SOUTH SALT LAKE CITY, UT US 84119 Contact: TONY PAYAN tpayan@arnoldmachinery.com T: (801)972-4000 F: (801)975-9434

### Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. Confirm oil type.

Depot: VOLVO8770 **Unique No:** 10966529 Signed: Don Baldridge Report Date: 10 Apr 2024



## **CONSTRUCTION EQUIPMENT**





