

Sample No: VCP443734
Oil Type: VOLVO WB 102

Job No: 700681 ALTA RENTS

SAMPLE	INFORMATION			
Sample Number		VCP443734	 	
Sample Date		04 Apr 2024		
Machine Hours		914	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		ATTENTION	 	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	88.8	 	
VOLVO	INATION			
CONTAM	INATIUN			
Water	%	NEG	 	
Silicon	ppm	■ 5	 	
Sodium	ppm	1	 	
Potassium	ppm	2	 	
WEAR M	ETALC			
_	E14F2			
Iron	ppm	■ 300	 	
Copper	ppm	42	 	
Lead	ppm	■0	 	
Tin	ppm	■ 2	 	
Aluminum	ppm	■0	 	
Chromium	ppm	■ 5	 	
Molybdenum	ppm	6	 	
Nickel	ppm	■ 3	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	11	 	
Vanadium	ppm	0	 	
ADDITIV	ES			
Calcium	ppm	713	 	
Magnesium	ppm	1 2	 	
Zinc	ppm	311	 	
Phosphorus	ppm	1414	 	
Barium		3	 	
	ppm	_	 	
Boron	ppm	236	 	



ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC
9601 BOGGY CREEK RD
ORLANDO, FL
US 32824
Contact: Robert LaPlante
robert.laplante@altg.com
T: (407)508-9736
F: (407)659-8720

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is higher than normal. Additive levels indicate the addition of a different brand, or type of oil. Confirm oil type.

Depot:VOLVO0096Unique No:10966536Signed:Don BaldridgeReport Date:10 Apr 2024

Contact/Location: Robert LaPlante - VOLVO0096



CONSTRUCTION EQUIPMENT





