

## CONSTRUCTION EQUIPMENT 25341 VOLVO A40G 353232 - FRONT AXLE



Sample No: VCP455261

Oil Type: VOLVO SUPER GEAR OIL 75W-80-GO102

**Job No:** 25341

VOLVO	INFORMATION			
	INFURMATIUR		<u></u>	
Sample Number		VCP455261		 
Sample Date		29 Mar 2024		 
Machine Hours		1378		 
Oil Hours		0		 
Oil Changed		Changed		 
Sample Status		NORMAL		 
OIL CON	NITION			
		- F4.6		 
Visc @ 40°C	cSt	<b>■</b> 51.6		 
VOLVO				
CONTAM	IINATION			
Water	%	NEG		 
Silicon	ppm	<b>14</b>		 
Sodium	ppm	■3		 
Potassium	ppm	<b>6</b>		 
Otassiani	ррііі			
VOLVO				
WEAR M	ETALS			
Iron	ppm	<b>134</b>		 
Copper	ppm	<b>2</b>		 
Lead	ppm	<b>0</b>		 
Tin	ppm	■0		 
Aluminum	ppm	<b>2</b>		 
Chromium	ppm	<b>2</b>		 
Molybdenum	ppm	■3		 
Nickel	ppm	<b>■&lt;1</b>		 
Titanium	ppm	<1		 
Silver	ppm	0		 
Manganese	ppm	<b>6</b>		 
Vanadium	ppm	<1		 
ADDITIV				 
_	[7			
Calcium	ppm	■97		 
Magnesium	ppm	<b>2</b>		 
Zinc	ppm	■ 32		 
Phosphorus	ppm	<b>2513</b>		 
Barium	ppm	<b>■</b> 0		 
Boron	ppm	<b>275</b>		 



218 - ASCENDUM MACHINERY INC - N. CHARLESTON 7235 CROSS COUNTRY RD. NORTH CHARLESTON, SC US 29418 Contact: MATT MITCHAM matt.mitcham@ascendummachinery.com T·

F: (843)414-1129

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO3387Unique No:10966554Signed:Don BaldridgeReport Date:10 Apr 2024



## **CONSTRUCTION EQUIPMENT**





