



# CONSTRUCTION EQUIPMENT

527926-20 VOLVO L90H 627131 - REAR AXLE



**Sample No:** VCP446079  
**Oil Type:** VOLVO  
**Job No:** 527926-20



## SAMPLE INFORMATION

Sample Number	VCP446079	---	---	---
Sample Date	04 Apr 2024	---	---	---
Machine Hours	755	---	---	---
Oil Hours	755	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

**ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC**  
 9601 BOGGY CREEK RD  
 ORLANDO, FL  
 US 32824  
 Contact: Robert LaPlante  
 robert.laplante@altg.com  
 T: (407)508-9736  
 F: (407)659-8720



## OIL CONDITION

Visc @ 40°C	cSt	█ 43.5	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 21	---	---	---
Sodium	ppm	█ 4	---	---	---
Potassium	ppm	█ 4	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



## WEAR METALS

Iron	ppm	█ 38	---	---	---
Copper	ppm	█ 128	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ 14	---	---	---
Aluminum	ppm	█ 2	---	---	---
Chromium	ppm	█ 3	---	---	---
Molybdenum	ppm	3	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	7	---	---	---
Vanadium	ppm	<1	---	---	---



## ADDITIVES

Calcium	ppm	4127	---	---	---
Magnesium	ppm	12	---	---	---
Zinc	ppm	1646	---	---	---
Phosphorus	ppm	1387	---	---	---
Barium	ppm	0	---	---	---
Boron	ppm	139	---	---	---

**Depot:** VOLVO0096  
**Unique No:** 10966563  
**Signed:** Don Baldrige  
**Report Date:** 10 Apr 2024



# CONSTRUCTION EQUIPMENT



## GRAPHS

