CONSTRUCTION EQUIPMENT 135982 VOLVO A40G 752154 - HYDRAULIC SYSTEM



Sample No:	VCP442493				
Oil Type:	{unknown}				
Job No:	135982				

VOLVO

	FORMATION				
		· · · · · · · · · · · · · · · · · · ·			_
Sample Number		VCP442493			
Sample Date		03 Apr 2024			
Machine Hours		530			
Oil Hours		0			
Oil Changed		Not Changd			
Sample Status		NORMAL			
OIL CONDI	ΓΙΩΝ				
		<u>.</u>	<u>.</u>	<u>.</u>	-
Visc @ 40°C	cSt	45.4			
Acid Number (AN)	mg KOH/g	0.43			
CONTAMIN					
	ATION				
Water	%	NEG			
Particles >4µm		500			

Particles >4µm		500	 	
Particles >6µm		140	 	
Particles >14µm		12	 	
ISO 4406:1999 (c)		16/14/11	 	
Silicon	ppm		 	
Sodium	ppm	0	 	
Potassium	ppm	1	 	

🎾 WEAR METALS

ppm	1			
ppm	2			
ppm	□<1			
ppm				
ppm	2			
ppm				
ppm	0			
ppm	0			
ppm	<1			
ppm	<1			
ppm	0			
ppm	<1			
	ppm ppm ppm ppm ppm ppm ppm ppm ppm	ppm 2 ppm <1	ppm 2 ppm <1	ppm 2 ppm <1

VOLVO

ADDIT	IVES			
Calcium	ppm	98	 	
Magnesium	ppm	<1	 	
Zinc	ppm	447	 	
Phosphorus	ppm	358	 	
Barium	ppm	<1	 	
Boron	ppm	0	 	



LATTIMORE MATERIALS/HOLCIM - ROSSER - LAFARGE 14242 S SH-34 SCURRY, TX US 75158 Contact: WALLACE WARREN wallace.warren@lafargeholcim.com T: F:

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is ISO 46 AW Hydraulic Oil. Please confirm the oil type and grade, and specify the brand of the oil on your next sample.All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

 Depot:
 LATSCU

 Unique No:
 10966993

 Signed:
 Wes Davis

 Report Date:
 11 Apr 2024

Contact/Location: WALLACE WARREN - LATSCU

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO

