CONSTRUCTION EQUIPMENT X18458 APAC VOLVO L180H 5518 - HYDRAULIC SYSTEM

Sample No:VCP444577Oil Type:VOLVO SUPER HYDRAULIC OIL 46Job No:X18458 APAC

SAMPLE INFORMATION

VOLVO

Sample Number	-	VCP444577	 	
Sample Date		02 Apr 2024	 	
Machine Hours		4008	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIL CONDI	TION			
Visc @ 40°C	cSt	42.8	 	
Acid Number (AN)	mg KOH/g	0.35	 	
CONTAMIN	IATION			
Water	%	NEG	 	

Water	%	NEG	 	
Particles >4µm		7400	 	
Particles >6µm		803	 	
Particles >14µm		37	 	
ISO 4406:1999 (c)		20/17/12	 	
Silicon	ppm	1	 	
Sodium	ppm	2	 	
Potassium	ppm	0	 	

🎾 WEAR METALS

Iron	ppm	2	 	
Copper	ppm	2	 	
Lead	ppm	0	 	
Tin	ppm		 	
Aluminum	ppm	0	 	
Chromium	ppm	1	 	
Molybdenum	ppm	0	 	
Nickel	ppm	0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	0	 	
Vanadium	ppm	0	 	

VOLVO

Calcium	ppm	85				
Magnesium	ppm	0				
Zinc	ppm	432				
Phosphorus	ppm	339				
Barium	ppm	0				
Boron	ppm	0				



SCOTT EQUIPMENT COMPANY LLC - Jackson 3860 I-55 South JACKSON, MS US 39212 Contact: DWIGHT MCDOUGAL DMCDOUGAL@SCOTTCOMPANIES.COM T: F: (601)326-3359

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

 Depot:
 VOLV08771

 Unique No:
 10968493

 Signed:
 Wes Davis

 Report Date:
 10 Apr 2024

CONSTRUCTION EQUIPMENT



💙 GRAPHS

VOLVO

