



CONSTRUCTION EQUIPMENT

700392 ALTA RENTS VOLVO A25G 752731 - REAR AXLE



Sample No: VCP455126
Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5
Job No: 700392 ALTA RENTS



SAMPLE INFORMATION

Sample Number	VCP455126	---	---	---
Sample Date	02 Apr 2024	---	---	---
Machine Hours	1259	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	ATTENTION	---	---	---

ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC
 9601 BOGGY CREEK RD
 ORLANDO, FL
 US 32824
 Contact: Robert LaPlante
 robert.laplante@altg.com
 T: (407)508-9736
 F: (407)659-8720



OIL CONDITION

Visc @ 40°C	cSt	● 86.0	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	■ 5	---	---	---
Sodium	ppm	■ 1	---	---	---
Potassium	ppm	■ 3	---	---	---



WEAR METALS

Iron	ppm	■ 305	---	---	---
Copper	ppm	■ 32	---	---	---
Lead	ppm	■ 0	---	---	---
Tin	ppm	■ <1	---	---	---
Aluminum	ppm	■ 0	---	---	---
Chromium	ppm	■ 6	---	---	---
Molybdenum	ppm	■ 9	---	---	---
Nickel	ppm	■ 4	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	■ 10	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	● 908	---	---	---
Magnesium	ppm	■ 2	---	---	---
Zinc	ppm	● 387	---	---	---
Phosphorus	ppm	● 1462	---	---	---
Barium	ppm	■ 9	---	---	---
Boron	ppm	● 259	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. This plus the additive levels indicates the addition of a different brand, or type of oil. Confirm oil type.

Depot: VOLVO0096
Unique No: 10969469
Signed: Don Baldrige
Report Date: 13 Apr 2024



CONSTRUCTION EQUIPMENT



GRAPHS

