



CONSTRUCTION EQUIPMENT

700724 RENTALS VOLVO A25G 75294 - FRONT AXLE



Sample No: VCP446390
Oil Type: {unknown}
Job No: 700724 RENTALS



SAMPLE INFORMATION

Sample Number	VCP446390	---	---	---
Sample Date	04 Apr 2024	---	---	---
Machine Hours	2592	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC
 9601 BOGGY CREEK RD
 ORLANDO, FL
 US 32824
 Contact: Robert LaPlante
 robert.laplante@altg.com
 T: (407)508-9736
 F: (407)659-8720



OIL CONDITION

Visc @ 40°C	cSt	█ 247	---	---	---
-------------	-----	-------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 6	---	---	---
Sodium	ppm	█ <1	---	---	---
Potassium	ppm	█ 0	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	█ 300	---	---	---
Copper	ppm	█ 12	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ 0	---	---	---
Chromium	ppm	█ 3	---	---	---
Molybdenum	ppm	7	---	---	---
Nickel	ppm	█ 1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	4	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	359	---	---	---
Magnesium	ppm	79	---	---	---
Zinc	ppm	222	---	---	---
Phosphorus	ppm	843	---	---	---
Barium	ppm	<1	---	---	---
Boron	ppm	70	---	---	---

Depot: VOLVO0096
Unique No: 10969499
Signed: Don Baldrige
Report Date: 13 Apr 2024



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

