

# CONSTRUCTION EQUIPMENT 687510 VOLVO A40G 752073 - DIESEL ENGINE



Sample No: VCP444108

Oil Type: VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3

Job No: 687510

CAMPLE IN	NFORMATION				
	AI UNMATION	VCD444400	V(CD 422 425		
Sample Number		VCP444108	VCP433435		
Sample Date		12 Mar 2024	30 Nov 2023		
Machine Hours		1131	527		
Oil Hours		500	527		
Oil Changed		Changed	Changed		
Sample Status		ATTENTION	ATTENTION		
VOLVO					
OIL CONDITION					
Visc @ 100°C	cSt	12.2	11.0		
Base Number (BN)	mg KOH/g	<b>■8.3</b>	5.4		
Oxidation (PA)	%	76	56		
CONTAMINATION					
_	VATION				
Water	%	NEG	NEG		
Soot %	%	■ 0.2	□ 0.2		
Nitration (PA)	%	68	83		
Sulfation (PA)	%	60	52		
Glycol	%	NEG	NEG		
Fuel	%	<1.0	□0.4		
Silicon	ppm	<b>10</b>	■30		
Sodium	ppm	<b>2</b>	<b>2</b>		
Potassium	ppm	<b>■ &lt;1</b>	<b>5</b>		
WEAR METALS					
Iron		<b>10</b>	<b>1</b> 7		
	ppm	■ 10 ■ 54	281		
Copper Lead	ppm	_			
	ppm	<b>1</b>	<b>3</b>		
Tin	ppm	<b>■</b> <1	3		
Aluminum	ppm	<b>2</b>	2		
Chromium	ppm	<b>□</b> <1	0		
Molybdenum Nickel	ppm	<b>■</b> 50	84		
	ppm	<b>2</b>	2		
Titanium	ppm	<1	0		
Silver	ppm	<b>0</b>	0		
Manganese	ppm	<b>■ &lt;1</b>	2		
Vanadium	ppm	<1	<1		
VOLVO					
ADDITION					
Calcium	ppm	■ 1846	<b>2132</b>		
Magnesium	ppm	<b>■</b> 554	61		
Zinc	ppm	<b>1249</b>	■1233		
Phosphorus	ppm	<b>1019</b>	1048		
Barium	ppm	<b>0</b>	<b>0</b>		
= =	L- L				



#### **RIPA AND ASSOCIATES**

10149 FISHER AVENUE TAMPA, FL US 33619 Contact: PM Services PMServices@ripaconstruction.com F:

### Diagnosis

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. The BN result indicates that there is suitable alkalinity remaining in the oil. Confirm oil type.

Depot: **RIPTAM Unique No:** 10970497 Signed: Don Baldridge Report Date: 14 Apr 2024

Contact/Location: PM Services ? - RIPTAM

ppm

Boron



## **CONSTRUCTION EQUIPMENT**





