



CONSTRUCTION EQUIPMENT

687011 VOLVO EC200EL 314968 - HYDRAULIC SYSTEM



Sample No: VCP440915
Oil Type: VOLVO SUPER HYDRAULIC OIL 46
Job No: 687011



SAMPLE INFORMATION

Sample Number	VCP440915	---	---	---
Sample Date	07 Mar 2024	---	---	---
Machine Hours	554	---	---	---
Oil Hours	554	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

RIPA AND ASSOCIATES

10149 FISHER AVENUE
TAMPA, FL
US 33619
Contact: ROBERT TURNER
rturner@ripatampa.com



OIL CONDITION

Visc @ 40°C	cSt	█ 42.8	---	---	---
Acid Number (AN)	mg KOH/g	█ 0.50	---	---	---

T:
F:



CONTAMINATION

Water	%	NEG	---	---	---
Particles >4µm		█ 3482	---	---	---
Particles >6µm		█ 1042	---	---	---
Particles >14µm		█ 100	---	---	---
ISO 4406:1999 (c)		19/17/14	---	---	---
Silicon	ppm	█ 2	---	---	---
Sodium	ppm	█ <1	---	---	---
Potassium	ppm	█ 0	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



WEAR METALS

Iron	ppm	█ 0	---	---	---
Copper	ppm	█ 7	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 0	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 0	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES


Calcium	ppm	█ 80	---	---	---
Magnesium	ppm	█ <1	---	---	---
Zinc	ppm	█ 463	---	---	---
Phosphorus	ppm	█ 365	---	---	---
Barium	ppm	█ <1	---	---	---
Boron	ppm	█ 0	---	---	---

Depot: RIPTAM
Unique No: 10975882
Signed: Wes Davis
Report Date: 12 Apr 2024




VOLVO GRAPHS

Ferrous Alloys




Non-ferrous Metals



Viscosity @ 40°C



Particle Count



Acid Number

