

CONSTRUCTION EQUIPMENT 701224 IAA VOLVO L90H 627228 - HYDRAULIC SYSTEM

Sample No: VCP446421

Oil Type: VOLVO SUPER HYDRAULIC OIL 46

Job No: 701224 IAA

Sample Number		VCP446421	 	
Sample Date		09 Apr 2024	 	
Machine Hours		0	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		ATTENTION	 	
OIL COND	ITION			
Visc @ 40°C	cSt	44.8	 	
Acid Number (AN)	mg KOH/g	0.40	 	
VOLVO				
CONTAM	NATION			
Water	%	NEG	 	
Particles >4µm	70	5729	 	
Particles >6µm		■ 1440	 	
Particles > 14µm		90	 	
ISO 4406:1999 (c)		20/18/14	 	
Silicon	ppm	<u>□</u> 1	 	
Sodium	ppm	□ <1	 	
Potassium	ppm	0	 	
	ρρ			
VOLVO	TALE		 	
WEAR MI	ETALS			
Iron	ppm	■ <1	 	
Copper	ppm	■ 0	 	
Lead	ppm	□ 0	 	
Tin	ppm	■ 0	 	
Aluminum	ppm	■ 0	 	
Chromium	ppm	■ 0	 	
Molybdenum	ppm	■0	 	
Nickel	ppm	■ 0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	□ 0	 	
Vanadium	ppm	0	 	



ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC 9601 BOGGY CREEK RD ORLANDO, FL

US 32824 Contact: Robert LaPlante robert.laplante@altg.com T: (407)508-9736

F: (407)659-8720

Diagnosis

We recommend you service the filters on this component. Resample at the next service interval to monitor.All component wear rates are normal. There is a light amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

 Depot:
 VOLVO0096

 Unique No:
 10975886

 Signed:
 Wes Davis

 Report Date:
 12 Apr 2024

Contact/Location: Robert LaPlante - VOLVO0096

68

■7 ■398

■313

0

0

ppm

ppm

ppm

ppm

ppm

ppm

Calcium

Zinc

Magnesium

Phosphorus

Barium

Boron



CONSTRUCTION EQUIPMENT





