

CONSTRUCTION EQUIPMENT 687484 VOLVO A30G 752866 - REAR AXLE



Sample No: VCP445389

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

Job No: 687484

CVMDIE	INFORMATION				
	. INI UNMATION				
Sample Number		VCP445389	VCP422140	VCP402760	
Sample Date		15 Mar 2024	05 Jul 2023	13 Feb 2023	
Machine Hours		2208	1096	526	
Oil Hours		1500	500	526	
Oil Changed		Not Changd	Not Changd	Changed	
Sample Status		NORMAL	NORMAL	NORMAL	
OIL CON	DITION				
Visc @ 40°C	cSt	201	206	■89.3	
VOLVO					
CONTAN	INATION				
Water	%	NEG	NEG	NEG	
Silicon	ppm	■3	112	■8	
Sodium		■ <1	< 1	2	
	ppm	0	2	_	
Potassium	ppm	U		5	
VOLVO					
WEAR M	TETALS				
Iron	ppm	195	□104	□318	
Copper	ppm	14	6	□ 13	
Lead	ppm	0	1 0	0	
Tin	ppm	■<1		□ <1	
Aluminum	ppm	■0	1	- <1	
Chromium	ppm	■3	2	6	
Molybdenum	ppm	1 4	4	8	
Nickel	ppm	2	<1	■3	
Titanium	ppm	0	0	0	
Silver	ppm	0	0	0	
Manganese	ppm	■ 4	3	□ 10	
Vanadium	ppm	<1	0	0	
Variation	Phili	`'	- U	U	
VOLVO					
ADDITIV	EZ				
Calcium	ppm	■313	277	■892	
Magnesium	ppm	■17	1 6	2	
Zinc	ppm	■158	■126	■368	
Phosphorus	ppm	1192	1066	1259	
Barium	ppm	1	0	3	
Boron	ppm	■ 162	174	□ 255	
	· · · ·				



RIPA AND ASSOCIATES

10149 FISHER AVENUE TAMPA, FL US 33619 Contact: ROBERT TURNER rturner@ripatampa.com T:

F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:RIPTAMUnique No:10976309Signed:Don BaldridgeReport Date:15 Apr 2024



CONSTRUCTION EQUIPMENT





