



# CONSTRUCTION EQUIPMENT

701224 IAA VOLVO L90H 627228 - TRANSMISSION (AUTO)



**Sample No:** VCP446397  
**Oil Type:** VOLVO AUTOMATIC TRANSMISSION FLUID AT102  
**Job No:** 701224 IAA



**ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC**  
 9601 BOGGY CREEK RD  
 ORLANDO, FL  
 US 32824  
 Contact: Robert LaPlante  
 robert.laplante@altg.com  
 T: (407)508-9736  
 F: (407)659-8720



## SAMPLE INFORMATION

Sample Number	VCP446397	---	---	---
Sample Date	09 Apr 2024	---	---	---
Machine Hours	832	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---



## OIL CONDITION

Visc @ 40°C	cSt	█ 29.5	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 10	---	---	---
Sodium	ppm	█ 4	---	---	---
Potassium	ppm	█ 0	---	---	---



## WEAR METALS

Iron	ppm	█ 107	---	---	---
Copper	ppm	█ 6	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ <1	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ <1	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 8	---	---	---
Vanadium	ppm	<1	---	---	---



## ADDITIVES

Calcium	ppm	█ 86	---	---	---
Magnesium	ppm	█ 3	---	---	---
Zinc	ppm	█ 40	---	---	---
Phosphorus	ppm	█ 218	---	---	---
Barium	ppm	█ 3	---	---	---
Boron	ppm	█ 65	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

**Depot:** VOLVO0096  
**Unique No:** 10976336  
**Signed:** Wes Davis  
**Report Date:** 12 Apr 2024



# CONSTRUCTION EQUIPMENT



## VOLVO GRAPHS

