CONSTRUCTION EQUIPMENT SPM689364 VOLVO L90H 626515 - HYDRAULIC SYSTEM

Sample No:VCP438176Oil Type:AW HYDRAULIC OIL ISO 46Job No:SPM689364

VOLVO

CONTAMINATION

%

ppm

ppm

ppm

SAMPLE INFORMATION							
Sample Number	VCP438176						
Sample Date	05 Apr 2024						
Machine Hours	2656						
Oil Hours	0						
Oil Changed	Not Changd						
Sample Status	NORMAL						
OIL CONDITION							
Visc @ 40°C cSt	42.4						
Acid Number (AN) mg KOH/g	0.30						

NEG

1239

17/13/10

68 🔳

6

4

0



IAA - INSURANCE AUTO AUCTIONS - AURORA 280 E SULLIVAN AURORA, IL US 60505 Contact: Service Manager

Diagnosis

T: F:

> Resample at the next service interval to monitor.All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

VOLVO

Potassium

Water

Silicon

Sodium

Particles >4µm

Particles >6µm

Particles >14µm

ISO 4406:1999 (c)

WEAR I	METALS			
Iron	ppm	4	 	
Copper	ppm	3	 	
Lead	ppm	2	 	
Tin	ppm	1	 	
Aluminum	ppm	1	 	
Chromium	ppm		 	
Molybdenum	ppm	1	 	
Nickel	ppm		 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	 <1	 	
Vanadium	ppm	<1	 	

VOLVO

Calcium	ppm	79					
Magnesium	ppm	4					
Zinc	ppm	428					
Phosphorus	ppm	369					
Barium	ppm	■<1					
Boron	ppm	0					

 Depot:
 INSAUR

 Unique No:
 10977336

 Signed:
 Wes Davis

 Report Date:
 15 Apr 2024

Report Id: INSAUR [WUSCAR] 06147258 (Generated: 04/15/2024 14:43:41) Rev: 1

Contact/Location: Service Manager - INSAUR

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO

