



CONSTRUCTION EQUIPMENT

TRANSPORT LEASING VOLVO L220H 2268 - REAR AXLE



Sample No: VCP440404
Oil Type: MOBIL MOBILFLUID 424
Job No: TRANSPORT LEASING



SAMPLE INFORMATION

Sample Number	VCP440404	VCP429827	VCP400157	VCP393730
Sample Date	28 Mar 2024	26 Jan 2024	31 Oct 2023	26 Apr 2023
Machine Hours	24936	23943	22857	21868
Oil Hours	0	0	0	0
Oil Changed	Changed	Changed	Changed	Changed
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL

ARNOLD MACHINERY COMPANY
 464 WASHINGTON STREET S
 TWIN FALLS, ID
 US 83301
 Contact: JANA E HYMAS
 jhymas@arnoldmachinery.com
 T: (208)733-1715
 F: (775)356-7152



OIL CONDITION

Visc @ 40°C	cSt	55.8	53.7	52.0	51.3
-------------	-----	-------------	------	------	------



CONTAMINATION

Water	%	NEG	NEG	NEG	NEG
Silicon	ppm	16	15	15	16
Sodium	ppm	<1	<1	<1	1
Potassium	ppm	0	0	0	0

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	7	5	7	10
Copper	ppm	0	0	0	0
Lead	ppm	0	0	0	0
Tin	ppm	0	<1	0	0
Aluminum	ppm	<1	<1	<1	1
Chromium	ppm	0	<1	0	<1
Molybdenum	ppm	5	0	<1	4
Nickel	ppm	0	0	0	0
Titanium	ppm	0	0	0	0
Silver	ppm	0	0	0	0
Manganese	ppm	<1	<1	0	<1
Vanadium	ppm	0	0	0	0



ADDITIVES

Calcium	ppm	3430	3315	3303	3242
Magnesium	ppm	76	21	27	46
Zinc	ppm	1424	1385	1337	1424
Phosphorus	ppm	1184	1147	1044	1126
Barium	ppm	0	0	0	0
Boron	ppm	114	109	114	111

Depot: VOLVO1835
Unique No: 10977822
Signed: Wes Davis
Report Date: 15 Apr 2024



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

