



CONSTRUCTION EQUIPMENT

701224 IAA VOLVO L90H 627228 - REAR AXLE



Sample No: VCP446380
Oil Type: VOLVO SUPER WET BRAKE TRANSAXLE OIL WB102
Job No: 701224 IAA



ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC
 9601 BOGGY CREEK RD
 ORLANDO, FL
 US 32824
 Contact: Robert LaPlante
 robert.laplante@altg.com
 T: (407)508-9736
 F: (407)659-8720



SAMPLE INFORMATION

Sample Number	VCP446380	---	---	---
Sample Date	09 Apr 2024	---	---	---
Machine Hours	832	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---



OIL CONDITION

Visc @ 40°C	cSt	█41.1	---	---	---
-------------	-----	-------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█16	---	---	---
Sodium	ppm	█2	---	---	---
Potassium	ppm	█3	---	---	---



WEAR METALS

Iron	ppm	█36	---	---	---
Copper	ppm	█24	---	---	---
Lead	ppm	█<1	---	---	---
Tin	ppm	█2	---	---	---
Aluminum	ppm	█3	---	---	---
Chromium	ppm	█2	---	---	---
Molybdenum	ppm	█2	---	---	---
Nickel	ppm	█<1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█2	---	---	---
Vanadium	ppm	<1	---	---	---



ADDITIVES

Calcium	ppm	█3963	---	---	---
Magnesium	ppm	█10	---	---	---
Zinc	ppm	█1657	---	---	---
Phosphorus	ppm	█1377	---	---	---
Barium	ppm	█1	---	---	---
Boron	ppm	█124	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO0096
Unique No: 10979120
Signed: Wes Davis
Report Date: 16 Apr 2024



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

