

## CONSTRUCTION EQUIPMENT

SWA512294-10 LIBERTY GENIE S125 S12511-3151 - REAR LEFT

Sample No: VCP438102

Oil Type: VOLVO PREMIUM GEAR OIL 80W-90 GL-5

**Job No:** SWA512294-10 LIBERTY

VOLVO	INFORMATIO	VI		
	INFORMATIO			
Sample Number		VCP438102	 	
Sample Date		09 Apr 2024	 	
Machine Hours		2744	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		ABNORMAL	 	
OIL CON	DITION			
Visc @ 40°C	cSt	<b>147</b>	 	
VOLVO				
CONTAM	INATION			
Water	%	NEG	 	
Silicon	ppm	<b>1</b> 4	 	
Sodium	ppm	<u> </u>	 	
Potassium	ppm	<b>■3</b>	 	
	P   P   1			
VOLVO	AFTAL C			
WEAR M	IE I ALS			
Iron	ppm	<b>453</b>	 	
Copper	ppm	<u> </u>	 	
Lead	ppm	<b>123</b>	 	
Tin	ppm	<b>■8</b>	 	
Aluminum	ppm	<b>■</b> 3	 	
Chromium	ppm	<b>6</b>	 	
Molybdenum	ppm	<b>-&lt;1</b>	 	
Nickel	ppm	<b>1</b>	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	<b>12</b>	 	
Vanadium	ppm	<1	 	
ADDITIV	IES			
Calcium	ppm	<b>169</b>	 	
Magnesium	ppm	<b>■</b> 3	 	
Zinc	ppm	<b>115</b>	 	
Phosphorus	ppm	<b>1343</b>	 	
Barium	ppm	<b>2</b>	 	
Boron	ppm	<b>■</b> 57	 	



## **ALTA EQUIPMENT COMPANY**

1035 WYLIE DRIVE BLOOMINGTON, IL US 61705 Contact: MIKE MARTIN mike.martin@altaequipment.com T: F:

## Diagnosis

The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor.Bearing and/or bushing wear is indicated. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO5054Unique No:10979141Signed:Sean FeltonReport Date:17 Apr 2024



## **CONSTRUCTION EQUIPMENT**





