

CONSTRUCTION EQUIPMENT
512280 LIBERTY GENIE S-65 S6011-22685 - REAR RIGHT FINAL DE

Sample No: VCP454254

Oil Type: **GEAR OIL SAE 80W90** 

Job No: **512280 LIBERTY** 

VOLVO	INCODMATIO	VI		
	INFORMATIO	N		
Sample Number		VCP454254	 	
Sample Date		03 Apr 2024	 	
Machine Hours		2050	 	
Oil Hours		2050	 	
Oil Changed		Changed	 	
Sample Status		SEVERE	 	
OIL CON	DITION			
Visc @ 40°C	cSt	<b>137</b>	 	
VISC @ 40 C	CSI	<b>137</b>	 	
VOLVO				
CONTAM	MINATION			
Water	%	NEG	 	
Silicon	ppm	<b>42</b>	 	
Sodium	ppm	<b>16</b>	 	
Potassium	ppm	1	 	
		_		
VOLVO	AFTAL C			
WEAR M	NE I ALS			
Iron	ppm	<b>459</b>	 	
Copper	ppm	<u> </u>	 	
Lead	ppm	▲ 585	 	
Tin	ppm	<b>■7</b>	 	
Aluminum	ppm	<b>6</b>	 	
Chromium	ppm	<b>■</b> 5	 	
Molybdenum	ppm	<b>0</b>	 	
Nickel	ppm	<b>■</b> 0	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	■8	 	
Vanadium	ppm	0	 	
ADDITIV	/ES			
Calcium	ppm	<b>34</b>	 	
Magnesium	ppm	<b>7</b>	 	
Zinc	ppm	<b>6</b> 4	 	
Phosphorus	ppm	228	 	
Barium	ppm	<b>26</b>	 	
Boron	ppm	<b>13</b>	 	
DOTOIT	phili	<b>1</b> 3		



## **ALTA EQUIPMENT COMPANY**

1035 WYLIE DRIVE BLOOMINGTON, IL US 61705 Contact: MIKE MARTIN mike.martin@altaequipment.com F:

## Diagnosis

The oil change at the time of sampling has been noted. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition.Bearing and/or bushing wear is indicated. There is no indication of any contamination in the oil. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

Depot: VOLVO5054 **Unique No:** 10980880 Signed: Jonathan Hester Report Date: 19 Apr 2024



## **CONSTRUCTION EQUIPMENT**





