



CONSTRUCTION EQUIPMENT

VOLVO L120H 633400 - COOLANT



Sample No: VCP438995
Oil Type: VOLVO COOLANT VCS (YELLOW)
Job No:



SAMPLE INFORMATION

Sample Number	VCP438995	VCP437223	---	---
Sample Date	12 Apr 2024	20 Feb 2024	---	---
Machine Hours	0	2033	---	---
Sample Status	NORMAL	NORMAL	---	---

CITY CARTING
 221 OLD GATE LN
 MILFORD, CT
 US 06460
 Contact: TAVINS BANKS
 tavins@citycart.net
 T: (203)223-3885
 F:



COOLANT CONDITION

pH	Scale 0-14	7.21	7.46	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	NT	NT	---	---
Percentage Glycol	%	49.6	49.5	---	---
Freezing Point	°C	-33	-33	---	---

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

Coolant Appearance	normal	normal	---	---
Coolant Color	Yllow	Yllow	---	---

Depot: CITMILCON
Unique No: 10980945
Signed: Doug Bogart
Report Date: 19 Apr 2024




CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

