



CONSTRUCTION EQUIPMENT

2882-1 VOLVO PENTA TAD570-72VE 7005348005 - COOLANT



Sample No: VCP445931
Oil Type: VOLVO COOLANT VCS (YELLOW)
Job No: 2882-1



SAMPLE INFORMATION

Sample Number	VCP445931	---	---	---
Sample Date	05 Apr 2024	---	---	---
Machine Hours	4008	---	---	---
Sample Status	NORMAL	---	---	---

MCCLUNG-LOGAN EQUIPMENT CO - BRIDGEVILLE
 17941 SUSSEX HIGHWAY
 BRIDGEVILLE, DE
 US 19933
 Contact: MATT CLARK
 MCLARK@mcclung-logan.com
 T: (302)337-3400
 F: (302)337-9083



COOLANT CONDITION

pH	Scale 0-14	■ 7.05	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 50.4	---	---	---
Freezing Point	°C	■ -35	---	---	---

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

Depot: VOLVO1023
Unique No: 10980946
Signed: Doug Bogart
Report Date: 19 Apr 2024



CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity



Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

