



# CONSTRUCTION EQUIPMENT

## VOLVO EC350EL 314240 - COOLANT



**Sample No:** VCP0007829  
**Oil Type:** VOLVO COOLANT VCS (YELLOW)  
**Job No:**



### SAMPLE INFORMATION

Sample Number	<b>VCP0007829</b>	VCP316382	---	---
Sample Date	<b>15 Apr 2024</b>	11 Aug 2021	---	---
Machine Hours	<b>2291</b>	1096	---	---
Sample Status	<b>NORMAL</b>	NORMAL	---	---

**ALTA EQUIPMENT COMPANY**  
 8750 PHILIPS HWY  
 JACKSONVILLE, FL  
 US 32256  
 Contact: TECHNICIAN ACCOUNT  
 catherine.anastasio@wearcheck.com  
 T:  
 F: (904)737-1260



### COOLANT CONDITION

pH	Scale 0-14	<b>7.97</b>	8.39	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	<b>NT</b>	NT	---	---
Percentage Glycol	%	<b>48.7</b>	49	---	---
Freezing Point	°C	<b>-31</b>	-35	---	---

### Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



### CONTAMINATION

Coolant Appearance	<b>normal</b>	normal	---	---
Coolant Color	<b>Yllow</b>	Yllow	---	---

**Depot:** VOLVO0092  
**Unique No:** 10982585  
**Signed:** Jonathan Hester  
**Report Date:** 23 Apr 2024



# CONSTRUCTION EQUIPMENT




## GRAPHS


### Iron/Tin/Silver




### Reserve Alkalinity



### Copper/Aluminum/Lead



### Freeze Point



### pH



### Nitrites

