



CONSTRUCTION EQUIPMENT

700695 RENTS VOLVO ECR355 314784 - REAR LEFT FINAL DRIVE



Sample No: VCP443787
Oil Type: GEAR OIL SAE 80W90
Job No: 700695 RENTS



SAMPLE INFORMATION

Sample Number	VCP443787	---	---	---
Sample Date	03 Apr 2024	---	---	---
Machine Hours	966	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	ABNORMAL	---	---	---

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: KENNY HANEY
khaney@flaglerce.com
T: (813)630-0077
F: (813)630-2233



OIL CONDITION

Visc @ 40°C	cSt	■ 207	---	---	---
-------------	-----	-------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	▲ 126	---	---	---
Sodium	ppm	■ <1	---	---	---
Potassium	ppm	■ 2	---	---	---

Diagnosis

We advise that you check all areas where dirt can enter the system. Resample at the next service interval to monitor. Gear wear is indicated. Elemental levels of silicon (Si) and aluminum (Al) indicate alumina-silicate (coarse dirt) ingress. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	▲ 531	---	---	---
Copper	ppm	■ 6	---	---	---
Lead	ppm	■ 1	---	---	---
Tin	ppm	■ <1	---	---	---
Aluminum	ppm	● 21	---	---	---
Chromium	ppm	▲ 14	---	---	---
Molybdenum	ppm	■ 2	---	---	---
Nickel	ppm	■ 2	---	---	---
Titanium	ppm	2	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	■ 7	---	---	---
Vanadium	ppm	<1	---	---	---



ADDITIVES

Calcium	ppm	■ 40	---	---	---
Magnesium	ppm	■ 3	---	---	---
Zinc	ppm	■ 8	---	---	---
Phosphorus	ppm	■ 512	---	---	---
Barium	ppm	■ 3	---	---	---
Boron	ppm	■ 18	---	---	---

Depot: VOLVO0093
Unique No: 10983545
Signed: Jonathan Hester
Report Date: 23 Apr 2024



CONSTRUCTION EQUIPMENT



GRAPHS

