



CONSTRUCTION EQUIPMENT

701221 HERC VOLVO ECR223 315400 - REAR LEFT FINAL DRIVE



Sample No: VCP443718
Oil Type: {unknown}
Job No: 701221 HERC



SAMPLE INFORMATION

Sample Number	VCP443718	---	---	---
Sample Date	15 Apr 2024	---	---	---
Machine Hours	852	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: KENNY HANEY
khaney@flaglerce.com
T: (813)630-0077
F: (813)630-2233



OIL CONDITION

Visc @ 40°C	cSt	█ 176	---	---	---
-------------	-----	-------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 24	---	---	---
Sodium	ppm	█ 1	---	---	---
Potassium	ppm	█ 3	---	---	---

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	█ 133	---	---	---
Copper	ppm	█ 1	---	---	---
Lead	ppm	█ 1	---	---	---
Tin	ppm	█ 1	---	---	---
Aluminum	ppm	█ 2	---	---	---
Chromium	ppm	█ 3	---	---	---
Molybdenum	ppm	2	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	4	---	---	---
Vanadium	ppm	<1	---	---	---



ADDITIVES

Calcium	ppm	13	---	---	---
Magnesium	ppm	2	---	---	---
Zinc	ppm	11	---	---	---
Phosphorus	ppm	314	---	---	---
Barium	ppm	3	---	---	---
Boron	ppm	0	---	---	---

Depot: VOLVO0093
Unique No: 10983572
Signed: Sean Felton
Report Date: 22 Apr 2024



CONSTRUCTION EQUIPMENT



GRAPHS

