

# CONSTRUCTION EQUIPMENT SPM688077 VOLVO A60H 340136 - DIESEL ENGINE



Sample No: VCP436177

Oil Type: DIESEL ENGINE OIL SAE 15W40

**Job No:** SPM688077

VOLVO				
SAMPLE II	NFORMATION			
Sample Number	-	VCP436177	 	
Sample Date		16 Mar 2024	 	
Machine Hours		14660	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIL CONDI	TION			
Visc @ 100°C	cSt	<b>12.8</b>	 	
		<b>6.1</b>	 	
Base Number (BN) Oxidation (PA)	mg KOH/g %	69	 	
Oxidation (PA)	70	09	 	
VOLVO				
CONTAMIN	NATION			
Water	%	NEG	 	
Soot %	%	■ 0.8	 	
Nitration (PA)	%	71	 	
Sulfation (PA)	%	67	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon	ppm	<b>5</b>	 	
Sodium	ppm	<b>■</b> 3	 	
Potassium	ppm	<b>□</b> 0	 	
VOLVO				
WEAR ME	TALS			
Iron	ppm	■32	 	
Copper	ppm	<b>2</b>	 	
Lead	ppm	3	 	
Tin	ppm	<b>1</b>	 	
Aluminum	ppm	<b>5</b>	 	
Chromium	ppm	<b>■&lt;1</b>	 	
Molybdenum	ppm	<b>79</b>	 	
Nickel	ppm	<b>■</b> <1	 	
Titanium	ppm	<b>0</b>	 	
Silver	ppm	<b>■</b> 0	 	
Manganese	ppm	<b>■&lt;1</b>	 	
Vanadium	ppm	<1	 	
ADDITIVE:	7			
Calcium	ppm	<b>1475</b>	 	
Magnesium	ppm	<b>452</b>	 	
Zinc	ppm	<b>1213</b>	 	
Phosphorus	ррт	<b>1021</b>	 	
Barium	ppm	<b>0</b>	 	
Boron	ppm	<b>181</b>	 	
231011	7711			

#### **BELSON STEEL**

1685 N STATE RTE 50 BOURBONNAIS, IL US 60914 Contact: M. POZAN mpozan@belsonsteel.com T: (815)932-7416 F:

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot:BELBOUUnique No:10989325Signed:Wes DavisReport Date:22 Apr 2024

Contact/Location: M. POZAN - BELBOU



## **CONSTRUCTION EQUIPMENT**





