



CONSTRUCTION EQUIPMENT

SPM688077 VOLVO A60H 340136 - REAR AXLE



Sample No: VCP436171
Oil Type: GEAR OIL SAE 80W90
Job No: SPM688077



SAMPLE INFORMATION

Sample Number	VCP436171	---	---	---
Sample Date	16 Mar 2024	---	---	---
Machine Hours	14660	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

BELSON STEEL
 1685 N STATE RTE 50
 BOURBONNAIS, IL
 US 60914
 Contact: M. POZAN
 mpozan@belsonsteel.com
 T: (815)932-7416
 F:



OIL CONDITION

Visc @ 40°C	cSt	█ 48.3	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 3	---	---	---
Sodium	ppm	█ 6	---	---	---
Potassium	ppm	█ 1	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	█ 196	---	---	---
Copper	ppm	█ 0	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 0	---	---	---
Chromium	ppm	█ 4	---	---	---
Molybdenum	ppm	█ 2	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 7	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█ 77	---	---	---
Magnesium	ppm	█ 0	---	---	---
Zinc	ppm	█ 25	---	---	---
Phosphorus	ppm	█ 2387	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 260	---	---	---

Depot: BELBOU
Unique No: 10990296
Signed: Sean Felton
Report Date: 24 Apr 2024



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

