

CONSTRUCTION EQUIPMENT SPM688077 VOLVO A60H 340136 - FRONT AXLE



Sample No: VCP436176

Oil Type: GEAR OIL SAE 80W90

Job No: SPM688077

SAMPLE	INFORMATION			
Sample Number		VCP436176	 	
Sample Date		16 Mar 2024	 	
Machine Hours		14660	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
		11011111111		
OIL CON	DITION			
Visc @ 40°C	cSt	46.8	 	
	CSt	40.8	 	
VOLVO				
CONTAN	IINATION			
Water	%	NEG	 	
Silicon	ppm	■3	 	
Sodium	ppm	4	 	
Potassium	ppm	2	 	
VOLVO	IETAL C			
WEAR M	IF LATZ			
Iron	ppm	262	 	
Copper	ppm	■0	 	
Lead	ppm	■ 0	 	
Tin	ppm	■0	 	
Aluminum	ppm	■<1	 	
Chromium	ppm	5	 	
Molybdenum	ppm	2	 	
Nickel	ppm	■1	 	
Titanium	ppm	0	 	
Silver	ppm	<1	 	
Manganese	ppm	■8	 	
Vanadium	ppm	0	 	
ADDITIV	ES			
Calcium	ppm	7	 	
Magnesium	ppm	■0	 	
Zinc	ppm	4	 	
Phosphorus	ppm	2301	 	
Barium	ppm	■0	 	
Boron	ppm	212	 	
	- I- I			

BELSON STEEL

1685 N STATE RTE 50 BOURBONNAIS, IL US 60914 Contact: M. POZAN mpozan@belsonsteel.com T: (815)932-7416 F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:BELBOUUnique No:10990310Signed:Sean FeltonReport Date:24 Apr 2024

Contact/Location: M. POZAN - BELBOU



CONSTRUCTION EQUIPMENT





