



CONSTRUCTION EQUIPMENT

VOLVO A45G 752043 - FRONT AXLE



Sample No: VCP437313
Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5
Job No:



ALTA EQUIPMENT COMPANY
 5151 DR MARTIN LUTHER KING BLVD
 FORT MYERS, FL
 US 33905
 Contact: TODD LARK
 tlark@altaequipfl.com
 T:
 F: (239)481-3302



SAMPLE INFORMATION

Sample Number	VCP437313	---	---	---
Sample Date	16 Apr 2024	---	---	---
Machine Hours	1632	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---



OIL CONDITION

Visc @ 40°C	cSt	█ 103	---	---	---
-------------	-----	-------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 5	---	---	---
Sodium	ppm	█ 1	---	---	---
Potassium	ppm	█ 3	---	---	---



WEAR METALS

Iron	ppm	█ 332	---	---	---
Copper	ppm	█ 0	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 0	---	---	---
Chromium	ppm	█ 4	---	---	---
Molybdenum	ppm	█ 7	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 13	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█ 165	---	---	---
Magnesium	ppm	█ 0	---	---	---
Zinc	ppm	█ 61	---	---	---
Phosphorus	ppm	█ 1446	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 295	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO0090
Unique No: 10990334
Signed: Sean Felton
Report Date: 24 Apr 2024



CONSTRUCTION EQUIPMENT



GRAPHS

