



CONSTRUCTION EQUIPMENT GRANULATION 2 - PUMP



Sample No: VCP374403

Oil Type: {unknown}

Job No:



SAMPLE INFORMATION

Sample Number	VCP374403	---	---	---
Sample Date	12 Apr 2024	---	---	---
Machine Hours	0	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---

LATTIMORE MATERIALS/HOLCIM - ROSSER - LAFARGE
14242 S SH-34
SCURRY, TX
US 75158
Contact: WALLACE WARREN
wallace.warren@lafargeholcim.com
T:
F:



OIL CONDITION

Visc @ 40°C	cSt	█ 152	---	---	---
-------------	-----	-------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 4	---	---	---
Sodium	ppm	█ 0	---	---	---
Potassium	ppm	█ 2	---	---	---

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	█ 3	---	---	---
Copper	ppm	█ <1	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ 2	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	26	---	---	---
Nickel	ppm	0	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	0	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	4	---	---	---
Magnesium	ppm	<1	---	---	---
Zinc	ppm	8	---	---	---
Phosphorus	ppm	121	---	---	---
Barium	ppm	0	---	---	---
Boron	ppm	0	---	---	---

Depot: LATSCU
Unique No: 10990725
Signed: Sean Felton
Report Date: 24 Apr 2024



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

