

CONSTRUCTION EQUIPMENT



Sample No: VCP386794
Oil Type: {unknown}

Job No:

SAMPLE	INFORMATIO	N		
Sample Number		VCP386794	 	
Sample Date			 	
Machine Hours		12 Apr 2024	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		NORMAL	 	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	157	 	
VOLVO				
CONTAN	MINATION			
Water	%	NEG	 	
Silicon	ppm	2	 	
Sodium	ppm	■ 0	 	
Potassium	ppm	1	 	
VOLVO	AETAL C			
WEAR N	JE I HLS			
Iron	ppm	10	 	
Copper	ppm	■ <1	 	
Lead	ppm		 	
Tin	ppm	■<1	 	
Aluminum	ppm	■2	 	
Chromium	ppm	■<1	 	
Molybdenum	ppm	1	 	
Nickel	ppm	<1	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	<1	 	
Vanadium	ppm	0	 	
VOLVO				
ADDITIV	771			
_	_			
Calcium	ppm	0	 	
Magnesium	ppm	<1	 	
Zinc	ppm	0	 	
Phosphorus	ppm	79	 	
Barium	ppm	0	 	
Boron	ppm	0	 	



LATTIMORE MATERIALS/HOLCIM - ROSSER - LAFARGE
14242 S SH-34
SCURRY, TX
US 75158
Contact: WALLACE WARREN
wallace.warren@lafargeholcim.com
T:
F:

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: LATSCU
Unique No: 10990726
Signed: Sean Felton
Report Date: 24 Apr 2024

Contact/Location: WALLACE WARREN - LATSCU



CONSTRUCTION EQUIPMENT





GRAPHS

