



# CONSTRUCTION EQUIPMENT

## VOLVO A30G 742385 - FRONT LEFT FINAL DRIVE



**Sample No:** VCP438707  
**Oil Type:** GEAR OIL SAE 80W140  
**Job No:**



### SAMPLE INFORMATION

Sample Number	VCP438707	---	---	---
Sample Date	09 Apr 2024	---	---	---
Machine Hours	5731	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

**SAIIA CONSTRUCTION LLC**  
 4400 LEWISBURG RD  
 BIRMINGHAM, AL  
 US 35207  
 Contact: STEPHANI BRITTON  
 sbritton@saiia.com;doug.bogart@wearcheck.com  
 T: (205)943-2268  
 F: (205)943-2269



### OIL CONDITION

Visc @ 40°C	cSt	█ 233	---	---	---
-------------	-----	-------	-----	-----	-----



### CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 3	---	---	---
Sodium	ppm	█ 0	---	---	---
Potassium	ppm	█ 0	---	---	---

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



### WEAR METALS

Iron	ppm	█ 143	---	---	---
Copper	ppm	█ 4	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 0	---	---	---
Chromium	ppm	█ 2	---	---	---
Molybdenum	ppm	█ 3	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 3	---	---	---
Vanadium	ppm	<1	---	---	---



### ADDITIVES

Calcium	ppm	█ 108	---	---	---
Magnesium	ppm	█ 22	---	---	---
Zinc	ppm	█ 63	---	---	---
Phosphorus	ppm	█ 848	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 141	---	---	---

**Depot:** SAIBIR  
**Unique No:** 10991801  
**Signed:** Don Baldrige  
**Report Date:** 24 Apr 2024



# CONSTRUCTION EQUIPMENT



## GRAPHS

