



CONSTRUCTION EQUIPMENT

702216 ALTA RENTS VOLVO A30G 753623 - TRANSMISSION (AUTO)



Sample No: VCP438423
Oil Type: VOLVO AT 102
Job No: 702216 ALTA RENTS



SAMPLE INFORMATION

Sample Number	VCP438423	---	---	---
Sample Date	17 Apr 2024	---	---	---
Machine Hours	749	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: KENNY HANEY
khaney@flaglerce.com
T: (813)630-0077
F: (813)630-2233



OIL CONDITION

Visc @ 40°C	cSt	█ 28.7	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 13	---	---	---
Sodium	ppm	█ 5	---	---	---
Potassium	ppm	█ 4	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



WEAR METALS

Iron	ppm	█ 22	---	---	---
Copper	ppm	█ 35	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ 6	---	---	---
Aluminum	ppm	█ 19	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ 4	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 3	---	---	---
Vanadium	ppm	<1	---	---	---



ADDITIVES

Calcium	ppm	█ 73	---	---	---
Magnesium	ppm	█ 1	---	---	---
Zinc	ppm	█ 5	---	---	---
Phosphorus	ppm	█ 182	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 78	---	---	---

Depot: VOLVO0093
Unique No: 10991911
Signed: Jonathan Hester
Report Date: 24 Apr 2024



CONSTRUCTION EQUIPMENT



GRAPHS

