



# CONSTRUCTION EQUIPMENT

SWO-071298 VOLVO A30G 742330 - COOLANT



**Sample No:** VCP449758  
**Oil Type:** VOLVO COOLANT VCS (YELLOW)  
**Job No:** SWO-071298



## SAMPLE INFORMATION

Sample Number	VCP449758	---	---	---
Sample Date	17 Apr 2024	---	---	---
Machine Hours	3480	---	---	---
Sample Status	NORMAL	---	---	---



## COOLANT CONDITION

pH	Scale 0-14	■ 7.57	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 50.4	---	---	---
Freezing Point	°C	■ -35	---	---	---



## CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

**COWIN EQUIPMENT COMPANY INC**  
 1501 HWY 78 EAST  
 OXFORD, AL  
 US 36203  
 Contact: MIKE PATTY  
 mpatty@cowin.com  
 T: (256)832-5053  
 F: (256)831-4295

## Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

**Depot:** COWOXF  
**Unique No:** 10991977  
**Signed:** Jonathan Hester  
**Report Date:** 24 Apr 2024



# CONSTRUCTION EQUIPMENT




## GRAPHS


### Iron/Tin/Silver




### Reserve Alkalinity



### Copper/Aluminum/Lead



### Freeze Point



### pH



### Nitrites

