

## CONSTRUCTION EQUIPMENT 12852 SDLG 640187 - FRONT AXLE



Sample No: VCE74168

**Oil Type:** GEAR OIL SAE 80W90

**Job No:** 12852

CVMDIE	INFORMATIO	V		
	. INFUNITATIO			
Sample Number		VCE74168	 	
Sample Date		18 Apr 2024	 	
Machine Hours		102	 	
Oil Hours		102	 	
Oil Changed		N/A	 	
Sample Status		NORMAL	 	
VOLVO				
OIL CONI	DITION			
Visc @ 40°C	cSt	<b>173</b>	 	
CONTAN	MINATION			
Water	%	NEG	 	
Silicon	ppm	■29	 	
Sodium	ppm	<b>42</b>	 	
Potassium	ppm	<b>2</b>	 	
VOLVO				
WEAR M	METALS			
Iron	ppm	<b>267</b>	 	
Copper	ppm	<b>■32</b>	 	
Lead	ppm	■8	 	
Tin	ppm	<u>2</u>	 	
Aluminum	ppm	7	 	
Chromium	ppm	 <b>■3</b>	 	
Molybdenum	ppm	O	 	
Nickel	ppm	■0	 	
Titanium	ppm	<1	 	
Silver	ppm	<1	 	
Manganese	ppm	<b>5</b>	 	
Vanadium	ppm	0	 	
	-1-1-			
VOLVO	IFC		 	
ADDITIV	FZ			
Calcium	ppm	<b>41</b>	 	
Magnesium	ppm	<b>12</b>	 	
Zinc	ppm	■28	 	
Phosphorus	ppm	<b>447</b>	 	
Barium	ppm	<b>13</b>	 	
Boron	ppm	0	 	



TRANSOURCE TRUCK & EQUIPMENT
901 EAST 60TH STREET NORTH
SIOUX FALLS, SD
US 57104
Contact: NATHAN MATZEN
nathan.matzen@transourceusa.com
T: (605)336-2000
F: (605)336-2248

## Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 VOLVO0035

 Unique No:
 10992560

 Signed:
 Wes Davis

 Report Date:
 23 Apr 2024



## **CONSTRUCTION EQUIPMENT**





