

CONSTRUCTION EQUIPMENT R24631 MAZZA VOLVO L45H 4122107 - TOP - REAR AXLE

Sample No: VCP237283

Oil Type: **TDH FLUID SAE 75W80**

Job No: R24631 MAZZA

SAMPLE INFORMATION					
Sample Number		VCP237283			
Sample Date		15 Apr 2024			
Machine Hours		11967			
Oil Hours		0			
Oil Changed		Changed			
_		NORMAL			
Sample Status		NORWAL			
VOLVO					
OIL COND	ITION				
Visc @ 40°C	cSt	41.9			
		_			
VOLVO	INATION				
CONTAM	INATIUN				
Water	%	NEG			
Silicon	ppm	12			
Sodium	ppm	0			
Potassium	ppm	2			
VOLVO					
WEAR M	TAIC				
_					
Iron	ppm	40			
Copper	ppm	1			
Lead	ppm	 <1			
Tin	ppm	■<1			
Aluminum	ppm	2			
Chromium	ppm	■<1			
Molybdenum	ppm	2			
Nickel	ppm	■ 3			
Titanium	ppm	<1			
Silver	ppm	0			
Manganese	ppm	1			
Vanadium	ppm	0			
VOLVO					
ADDITIV	Z				
Calcium	ppm	2149			
Magnesium	ppm	24			
Zinc	ppm	■1082			
Phosphorus	ppm	■945			
Barium	ppm	■0			
Boron	ppm	77			
231011	PPIII				



HOFFMAN EQUIPMENT INC

300 S RANDOLPHVILLE RD PISCATAWAY, NJ US 08854 Contact: IOANA BODOCHI ioana.bodochi@hoffmanequip.com T:

F: (732)968-8371

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) TDH FLUID SAE 75W80. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: **HOFPISNJ Unique No:** 10993493 Signed: Wes Davis Report Date: 24 Apr 2024

Contact/Location: IOANA BODOCHI - HOFPISNJ



CONSTRUCTION EQUIPMENT





