



# CONSTRUCTION EQUIPMENT

R24631 MAZZA VOLVO L45H 4122107 - TOP - REAR AXLE



**Sample No:** VCP237194  
**Oil Type:** TDH FLUID SAE 75W80  
**Job No:** R24631 MAZZA



## SAMPLE INFORMATION

Sample Number	VCP237194	---	---	---
Sample Date	15 Apr 2024	---	---	---
Machine Hours	11967	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

**HOFFMAN EQUIPMENT INC**  
300 S RANDOLPHVILLE RD  
PISCATAWAY, NJ  
US 08854  
Contact: ANTHONY NALEWAJKO  
anthony.nalewajko@hoffmanequip.com  
T: (732)752-3600  
F: (732)968-8371



## OIL CONDITION

Visc @ 40°C	cSt	█42.2	---	---	---
-------------	-----	-------	-----	-----	-----



## CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█12	---	---	---
Sodium	ppm	█0	---	---	---
Potassium	ppm	█2	---	---	---



## WEAR METALS

Iron	ppm	█40	---	---	---
Copper	ppm	█1	---	---	---
Lead	ppm	█<1	---	---	---
Tin	ppm	█<1	---	---	---
Aluminum	ppm	█2	---	---	---
Chromium	ppm	█<1	---	---	---
Molybdenum	ppm	█2	---	---	---
Nickel	ppm	█3	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█1	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	█2166	---	---	---
Magnesium	ppm	█25	---	---	---
Zinc	ppm	█1084	---	---	---
Phosphorus	ppm	█942	---	---	---
Barium	ppm	█0	---	---	---
Boron	ppm	█77	---	---	---

## Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) TDH FLUID SAE 75W80. Please confirm.  
All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

**Depot:** HOFPISNJ  
**Unique No:** 10993494  
**Signed:** Wes Davis  
**Report Date:** 24 Apr 2024



# CONSTRUCTION EQUIPMENT



## VOLVO GRAPHS

