Sample No: VCP438866

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

**Job No:** SWA538928 PALM BEACH

VOLVO SAMPLE	INFORMATION	N		
Sample Number		VCP438866	 	
Sample Date		18 Apr 2024	 	
Machine Hours		3858	 	
		0		
Oil Changed			 	
Oil Changed		Changed		
Sample Status		ATTENTION	 	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	52.2	 	
VOLVO	IINATION			
	IINATION			
Water	%	NEG	 	
Silicon	ppm	<b>6</b>	 	
Sodium	ppm	■2	 	
Potassium	ppm	<b>6</b>	 	
WEAR M	IFTAI S			
_		<b>257</b>		
Iron	ppm		 	
Copper	ppm	<b>4</b>	 	
Lead	ppm	<b></b>		
Tin	ppm	<b>■</b> <1		
Aluminum	ppm	<b>2</b>	 	
Chromium	ppm	<b>4</b>	 	
Molybdenum	ppm	3	 	
Nickel	ppm	<b>1</b>	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	<b>12</b>		
Vanadium	ppm	<1	 	
VOLVO				
ADDITIV	ES			
Calcium	ppm	<b>49</b>	 	
Magnesium	ppm	<b>1</b> 2	 	
Zinc	ppm	28	 	
Phosphorus	ppm	2483	 	
Barium	ppm	■0	 	
Boron	ppm	<b>231</b>	 	
20.011	PPIII			



## PALM BEACH AGGREGATES INC PO BOX 700, 20125 STATE RD 80

LOXAHATCHEE, FL US 33470

Contact: WILLIAM GONZALEZ wgonzalez@palmbeachag.com

T: (561)723-0194 F: (561)798-5380

## Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. This plus the additive levels indicates the addition of a different brand, or type of oil. Confirm oil type.

Depot:PALLOXUnique No:10993502Signed:Don BaldridgeReport Date:25 Apr 2024



## **CONSTRUCTION EQUIPMENT**





