



# CONSTRUCTION EQUIPMENT

G08594 VOLVO L70H 624493 - COOLANT



**Sample No:** VCP438321  
**Oil Type:** {unknown}  
**Job No:** G08594



## SAMPLE INFORMATION

Sample Number	VCP438321	---	---	---
Sample Date	18 Apr 2024	---	---	---
Machine Hours	1759	---	---	---
Sample Status	NORMAL	---	---	---

**HOFFMAN EQUIPMENT - DEPTFORD**  
 1330 HURFFVILLE ROAD  
 DEPTFORD, NJ  
 US 08096  
 Contact: TAMMY SANDORA  
 tammy.sandora@hoffmanequip.com  
 T: (856)227-6400  
 F: (856)227-0046



## COOLANT CONDITION

pH	Scale 0-14	■ 7.52	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 49.5	---	---	---
Freezing Point	°C	■ -33	---	---	---

## Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



## CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yellow	---	---	---

**Depot:** VOLVO8880  
**Unique No:** 10993679  
**Signed:** Jonathan Hester  
**Report Date:** 25 Apr 2024



# CONSTRUCTION EQUIPMENT



## VOLVO GRAPHS

