



CONSTRUCTION EQUIPMENT

VOLVO A25G 742401 - COOLANT



Sample No: VCP0007821

Oil Type: {unknown}

Job No:



SAMPLE INFORMATION

Sample Number	VCP0007821	---	---	---
Sample Date	03 Apr 2024	---	---	---
Machine Hours	0	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT COMPANY

8750 PHILIPS HWY
JACKSONVILLE, FL
US 32256

Contact: TECHNICIAN ACCOUNT
catherine.anastasio@wearcheck.com

T:
F: (904)737-1260



COOLANT CONDITION

pH	Scale 0-14	■ 7.42	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 50.2	---	---	---
Freezing Point	°C	■ -35	---	---	---

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

Depot: VOLVO0092
Unique No: 10994093
Signed: Jonathan Hester
Report Date: 25 Apr 2024

Submitted By: TECHNICIAN ACCOUNT



CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity



Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

