



# CONSTRUCTION EQUIPMENT

## X59915 ELGIN PELICA NP42774 - REAR LEFT WHEEL HUB



**Sample No:** VCP438239  
**Oil Type:** MOBIL SHC 629  
**Job No:** X59915



### SAMPLE INFORMATION

Sample Number	VCP438239	---	---	---
Sample Date	17 Apr 2024	---	---	---
Machine Hours	181	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

**SCOTT EQUIPMENT COMPANY LLC - Saint Rose**  
 PO BOX 997  
 SAINT ROSE, LA  
 US 70087  
 Contact: STEPHEN SALMERON  
 ssalmeron@scottcompanies.com  
 T: (504)461-0961  
 F: (504)461-0970



### OIL CONDITION

Visc @ 40°C	cSt	█ 154	---	---	---
-------------	-----	-------	-----	-----	-----



### CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 23	---	---	---
Sodium	ppm	█ 0	---	---	---
Potassium	ppm	█ 0	---	---	---

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



### WEAR METALS

Iron	ppm	█ 86	---	---	---
Copper	ppm	█ 7	---	---	---
Lead	ppm	█ 26	---	---	---
Tin	ppm	<1	---	---	---
Aluminum	ppm	█ <1	---	---	---
Chromium	ppm	█ 2	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 3	---	---	---
Vanadium	ppm	0	---	---	---



### ADDITIVES

Calcium	ppm	█ 17	---	---	---
Magnesium	ppm	█ 0	---	---	---
Zinc	ppm	█ 0	---	---	---
Phosphorus	ppm	█ 426	---	---	---
Barium	ppm	█ 8	---	---	---
Boron	ppm	█ 0	---	---	---

**Depot:** SCOSAI  
**Unique No:** 10994856  
**Signed:** Jonathan Hester  
**Report Date:** 26 Apr 2024



# CONSTRUCTION EQUIPMENT



## GRAPHS

