



# CONSTRUCTION EQUIPMENT

## 337558 - WET DISC BRAKE



**Sample No:** VCP445483  
**Oil Type:** {unknown}  
**Job No:** 337558



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC  
 8418 PALM RIVER ROAD  
 TAMPA, FL  
 US 33619  
 Contact: BILL PYLES  
 wpyles@altaequipfl.com  
 T: (407)375-5788  
 F: (813)630-2233



### SAMPLE INFORMATION

Sample Number	VCP445483	---	---	---
Sample Date	22 Apr 2024	---	---	---
Machine Hours	1662	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---



### OIL CONDITION

Visc @ 40°C	cSt	43.0	---	---	---
-------------	-----	------	-----	-----	-----



### CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	8	---	---	---
Sodium	ppm	0	---	---	---
Potassium	ppm	0	---	---	---



### WEAR METALS

Iron	ppm	11	---	---	---
Copper	ppm	5	---	---	---
Lead	ppm	0	---	---	---
Tin	ppm	0	---	---	---
Aluminum	ppm	2	---	---	---
Chromium	ppm	<1	---	---	---
Molybdenum	ppm	0	---	---	---
Nickel	ppm	0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	<1	---	---	---
Vanadium	ppm	0	---	---	---



### ADDITIVES

Calcium	ppm	66	---	---	---
Magnesium	ppm	0	---	---	---
Zinc	ppm	431	---	---	---
Phosphorus	ppm	337	---	---	---
Barium	ppm	0	---	---	---
Boron	ppm	0	---	---	---

### Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

**Depot:** VOLVO0093  
**Unique No:** 10994873  
**Signed:** Jonathan Hester  
**Report Date:** 26 Apr 2024



# CONSTRUCTION EQUIPMENT



## VOLVO GRAPHS

