

CONSTRUCTION EQUIPMENT 537144 VOLVO A40G 353375 - FRONT AXLE



Sample No: VCP449542

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

Job No: 537144

CAMDIE	INFORMATION				
	INFURMATION				
Sample Number		VCP449542	VCP412078	VCP417714	
Sample Date		18 Apr 2024	07 Sep 2023	14 Jul 2023	
Machine Hours		4458	2328	1524	
Oil Hours		0	0	0	
Oil Changed		Changed	Not Changd	Changed	
Sample Status		NORMAL	NORMAL	ATTENTION	
OIL CON	DITION				
Visc @ 40°C	cSt	286	■289	52.4	
VOLVO					
CONTAN	INATION				
Water	%	NEG	NEG	NEG	
Silicon	ppm	■3	1 4	1 6	
Sodium		0	= <1	4	
Potassium	ppm	0	2	8	
Potassium	ppm			<u> </u>	
VOLVO					
WEAR N	1ETALS				
Iron	ppm	■94	7 2	472	
Copper	ppm	-<1	0	2	
Lead	ppm	■ 0	0		
Tin	ppm	■ 0	0	- <1	
Aluminum	ppm	■ 0	0	- <1	
Chromium	ppm	1	- <1	7	
Molybdenum	ppm	2	3	7	
Nickel	ppm	■0	0	1	
Titanium	ppm	0	0	0	
Silver	ppm	0	0	0	
Manganese	ppm	■ 3	1 2	□14	
Vanadium	ppm	0	0	0	
VOLVO	IFC				
ADDITIV	E2				
Calcium	ppm	71	7 9	6 0	
Magnesium	ppm	16	□16	■0	
Zinc	ppm	41	41	34	
Phosphorus	ppm	1141	□1090	2632	
Barium	ppm	0	0	□0	
Boron	ppm	195	□ 207	321	



ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC
9601 BOGGY CREEK RD
ORLANDO, FL
US 32824
Contact: Robert LaPlante
robert.laplante@altg.com
T: (407)508-9736
F: (407)659-8720

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0096Unique No:10994886Signed:Jonathan HesterReport Date:26 Apr 2024

Contact/Location: Robert LaPlante - VOLVO0096



CONSTRUCTION EQUIPMENT





GRAPHS

