



# CONSTRUCTION EQUIPMENT

702724 HERC VOLVO EC200 314670 - REAR RIGHT FINAL DRIVE



**Sample No:** VCP451297  
**Oil Type:** VOLVO PREMIUM GEAR OIL 85W-140 GL-5  
**Job No:** 702724 HERC



**ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC**  
 9601 BOGGY CREEK RD  
 ORLANDO, FL  
 US 32824  
 Contact: Robert LaPlante  
 robert.laplante@altg.com  
 T: (407)508-9736  
 F: (407)659-8720



## SAMPLE INFORMATION

Sample Number	VCP451297	---	---	---
Sample Date	21 Apr 2024	---	---	---
Machine Hours	746	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---



## OIL CONDITION

Visc @ 40°C	cSt	█ 162	---	---	---
-------------	-----	-------	-----	-----	-----



## CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 11	---	---	---
Sodium	ppm	█ <1	---	---	---
Potassium	ppm	█ 6	---	---	---



## WEAR METALS

Iron	ppm	█ 290	---	---	---
Copper	ppm	█ 1	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ 2	---	---	---
Chromium	ppm	█ 2	---	---	---
Molybdenum	ppm	█ 2	---	---	---
Nickel	ppm	█ 1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 5	---	---	---
Vanadium	ppm	<1	---	---	---



## ADDITIVES

Calcium	ppm	█ 10	---	---	---
Magnesium	ppm	█ 1	---	---	---
Zinc	ppm	█ 21	---	---	---
Phosphorus	ppm	█ 277	---	---	---
Barium	ppm	█ 2	---	---	---
Boron	ppm	█ 0	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

**Depot:** VOLVO0096  
**Unique No:** 11002495  
**Signed:** Wes Davis  
**Report Date:** 30 Apr 2024



# CONSTRUCTION EQUIPMENT



## VOLVO GRAPHS

