



CONSTRUCTION EQUIPMENT

700877 DIPRO CATERPILLAR 982M 2686 - REAR AXLE



Sample No: VCP446957
Oil Type: CAT TDTO 30W
Job No: 700877 DIPRO



SAMPLE INFORMATION

Sample Number	VCP446957	VCP452311	VCP403879	---
Sample Date	18 Apr 2024	28 Dec 2023	19 Jan 2023	---
Machine Hours	14054	12902	10401	---
Oil Hours	2000	500	2000	---
Oil Changed	Changed	Changed	Changed	---
Sample Status	NORMAL	NORMAL	NORMAL	---

ALTA EQUIPMENT COMPANY - METRO WEST
 56195 PONTIAC TRAIL
 NEW HUDSON, MI
 US 48165
 Contact: PAUL CONZ
 paul.conz@altg.com
 T:
 F: (248)356-2029



OIL CONDITION

Visc @ 40°C	cSt	98.9	99.7	90.0	---
-------------	-----	-------------	------	------	-----



CONTAMINATION

Water	%	NEG	NEG	NEG	---
Silicon	ppm	7	6	2	---
Sodium	ppm	0	0	6	---
Potassium	ppm	2	1	23	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	24	60	21	---
Copper	ppm	3	9	1	---
Lead	ppm	<1	0	4	---
Tin	ppm	<1	0	1	---
Aluminum	ppm	2	2	0	---
Chromium	ppm	<1	<1	1	---
Molybdenum	ppm	<1	0	<1	---
Nickel	ppm	<1	0	<1	---
Titanium	ppm	<1	0	<1	---
Silver	ppm	0	0	<1	---
Manganese	ppm	<1	0	<1	---
Vanadium	ppm	<1	0	<1	---



ADDITIVES

Calcium	ppm	3104	3068	714	---
Magnesium	ppm	13	11	20	---
Zinc	ppm	1238	1313	458	---
Phosphorus	ppm	1070	1075	284	---
Barium	ppm	1	0	0	---
Boron	ppm	0	0	<1	---

Depot: VOLVO2990
Unique No: 11002502
Signed: Wes Davis
Report Date: 29 Apr 2024



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

