



# CONSTRUCTION EQUIPMENT

A12512 GEN ASPHALT VOLVO ECR235E 314290 - REAR LEFT FINAL DRIVE



**Sample No:** VCP438186  
**Oil Type:** MOBIL MOBILUBE HD 80W90  
**Job No:** A12512 GEN ASPHALT



## SAMPLE INFORMATION

Sample Number	<b>VCP438186</b>	VCP289195	---	---
Sample Date	<b>21 Apr 2024</b>	05 Oct 2020	---	---
Machine Hours	<b>2515</b>	730	---	---
Oil Hours	<b>1000</b>	730	---	---
Oil Changed	<b>Changed</b>	Changed	---	---
Sample Status	<b>NORMAL</b>	NORMAL	---	---

**HOFFMAN EQUIPMENT - LIONVILLE**  
 120 GORDON DRIVE  
 LIONVILLE, PA  
 US 19341  
 Contact: JIM FEHR  
 jim.fehr@hoffmanequip.com  
 T: (610)363-9200  
 F: (610)594-0829



## OIL CONDITION

Visc @ 40°C	cSt	<b>305</b>	166	---	---
-------------	-----	------------	-----	-----	-----



## CONTAMINATION

Water	%	<b>NEG</b>	NEG	---	---
Silicon	ppm	<b>42</b>	11	---	---
Sodium	ppm	<b>&lt;1</b>	0	---	---
Potassium	ppm	<b>5</b>	2	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



## WEAR METALS

Iron	ppm	<b>210</b>	139	---	---
Copper	ppm	<b>1</b>	<1	---	---
Lead	ppm	<b>&lt;1</b>	<1	---	---
Tin	ppm	<b>&lt;1</b>	<1	---	---
Aluminum	ppm	<b>11</b>	0	---	---
Chromium	ppm	<b>4</b>	2	---	---
Molybdenum	ppm	<b>1</b>	1	---	---
Nickel	ppm	<b>&lt;1</b>	0	---	---
Titanium	ppm	<b>2</b>	<1	---	---
Silver	ppm	<b>0</b>	<1	---	---
Manganese	ppm	<b>3</b>	3	---	---
Vanadium	ppm	<b>&lt;1</b>	0	---	---



## ADDITIVES

Calcium	ppm	<b>36</b>	61	---	---
Magnesium	ppm	<b>7</b>	2	---	---
Zinc	ppm	<b>19</b>	36	---	---
Phosphorus	ppm	<b>1006</b>	436	---	---
Barium	ppm	<b>2</b>	3	---	---
Boron	ppm	<b>177</b>	4	---	---

**Depot:** VOLVO8879  
**Unique No:** 11002507  
**Signed:** Sean Felton  
**Report Date:** 30 Apr 2024



# CONSTRUCTION EQUIPMENT



## GRAPHS

